

INFORMACIÓN SOBRE USO SEGURO DE SVHC

INFORMACIÓN SOBRE EL ARTÍCULO 33 DE REACH EN RELACIÓN CON LAS SUSTANCIAS EXTREMADAMENTE PREOCUPANTES

Estimado cliente:

El artículo 33(1) del Reglamento REACH (Reg. 1907/2006/CE) tiene como objetivo permitir que los clientes de productos suministrados tomen las medidas de gestión de riesgos pertinentes a causa de la presencia en los artículos de las sustancias extremadamente preocupantes (SVHC) indicadas en la lista de candidatos para la autorización, con el fin de garantizar su uso seguro.

FORD apoya los objetivos de REACH en general y el artículo 33(1) específicamente, que son coherentes con nuestro propio compromiso de promocionar la fabricación, manipulación y uso responsables de nuestros productos.

Identificación de las SVHC

Según nuestros conocimientos basados en la información obtenida de nuestra cadena de suministro y los datos de nuestros propios productos, las SVHC presentes en los artículos componentes en cantidades superiores al 0,1 % en peso son las que se muestran en la «Lista de SVHC» correspondiente al vehículo/pieza relevante.

Información específica sobre uso seguro para artículos que contengan SVHC

Si procede, la información específica sobre uso seguro para artículos que contienen SVHC se añade a la «Lista de SVHC» del vehículo/pieza relevante.

Información general sobre uso seguro para los artículos

Cada vehículo FORD tiene un manual del propietario, que incluye información sobre el uso seguro para los propietarios/operadores del vehículo. La información de FORD sobre reparación y mantenimiento de vehículos y piezas originales también incluye información sobre el uso seguro para el personal de mantenimiento.

Cuando están presentes en las piezas de este vehículo, las SVHC que se muestran en la «Lista de SVHC» correspondiente al vehículo/pieza relevante se incorporan de forma que se reduzca al mínimo la exposición potencial para los clientes, y es posible excluir el peligro para los seres humanos o el medio ambiente siempre que el vehículo y sus piezas se utilicen de la manera prevista, y que cualquier reparación, servicio y mantenimiento se lleve a cabo según las instrucciones técnicas para esas actividades y las buenas prácticas estándares del sector.

Un vehículo al final de su vida útil solo se puede desechar legalmente en la Unión Europea en una instalación de tratamiento autorizada (ATF). Las piezas de

vehículos deben desecharse de conformidad con las leyes aplicables localmente y las indicaciones de las autoridades locales.

Modelo: Ford Explorer

Lista de SVHC basada en la lista de candidatos de ECHA del 1 de enero de 2026

Información específica sobre uso seguro para artículos que contengan SVHC

No es necesaria información específica sobre uso seguro. Siga la información general sobre uso seguro de los artículos.

Commodity	REACH SVHCs
Accessories	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
Body and Security Electronics	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Body Covers and Ornamentation	Bumetrizole [3896-11-5]
Body Side InteriorTrim (Hard Trim)	C,C'-azodi(formamide) [123-77-3]
Brakes	Lead [7439-92-1]
	TBBA [79-94-7]
Bumpers and Spoilers	Diocetyl tin dilaurate [3648-18-8]
	Lead [7439-92-1]
Climate	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Closures and Lids BIW	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
Closures and Lids Mechanisms	Lead [7439-92-1]
Coil Spring (Front, Rear)	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Console Floor/Rear	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Cooling	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]

	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Driver Controls	Lead [7439-92-1]
EDS	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Electrified Drivetrain Systems	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Fixed Glazing	Bumetrizole [3896-11-5]
Front / Rear Door Trim	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Hybrid Technology	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
I/S Mirror	Lead [7439-92-1]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
IP Substrate and Ducts	Lead [7439-92-1]
Latches - Hood, Decklid and Liftgate Latches	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Latches - Side Door/Latch Mini Module	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Lower Body Structure	Lead [7439-92-1]
Mirrors	Cyclohexane-1,2-dicarboxylic anhydride [85-42-7]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
	TBBA [79-94-7]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]

	Lead [7439-92-1]
Pedals	Lead [7439-92-1]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	TBBA [79-94-7]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	Lead [7439-92-1]
Restraint	Lead [7439-92-1]
Safety Electronics	Lead [7439-92-1]
Seating	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Triphenyl-phosphate [115-86-6]
Seats - Structures	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Shock Absorbers	Lead [7439-92-1]
Side Air Bag (SAB) and Curtain Air Bag (CAB)	Lead [7439-92-1]
Side Door Mechanisms	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Steering	Lead [7439-92-1]
	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8]
Suspension Frames and Mountings	2-Methylimidazole [693-98-1]
	Bumetrizole [3896-11-5]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Switches - General Use	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Upper Body Structure	Bumetrizole [3896-11-5]
Wash-Wipe	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	TBBA [79-94-7]
Wheels Tires Jacks and Equipment	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Lead [7439-92-1]

